



TECHNICAL BULLETIN

Support Number: 513-874-3733
Fax: 513-874-6232
Web Site: www.hamiltonsafe.com
Email: support@hamiltonsafe.com

Author: Terry Stroop	Bulletin # SB-1013
Verification: Todd Lefevers	Date Issued: 8-22-12
Product: 80 UC Depository Heads	Date Revised:

Subject:
Night Depository Heads Bronze Bushing Retaining Spacer

All,

There have been 4 reports of the axle bronze bushing on lock side of 80UC night depositories bucket coming loose on models with serial #16977-N to #17203-N (4/4/12 thru 8/07/12). Please make sure that **any installation** that your dealership has been involved in verifies the correction or notifications to the end user.

Hamilton is offering the following recommended upgrade available on our 80UC Night Head:

Bronze Bushing Spacer:
Part Number: B6873
Kit also includes instructions

All New 80UC Heads Shipped After 8/08/12 and With a Serial Number of #17204-N and Higher Will Have a Stainless Steel Spacer Welded in Place.