



TECHNICAL BULLETIN

Support Number: 513-874-3733
Fax: 513-874-6232
Web Site: www.hamiltonsafe.com
Email: support@hamiltonsafe.com

Author: Terry Stroop	Bulletin # SB-1015
Verification: Todd Lefevers	Date Issued: 4-8-13
Product: 98RH Depository Heads	Date Revised:

Subject:
Night Depository Heads Bronze Bushing Retaining Spacer Reinstall

All,

There have been few reports of the axle bronze bushing on lock side of 98RH night depositories bucket coming loose on models with serial #2458-N to #2524-N (2/27/12 thru 8/13/12). Please make sure that **any installation** that your dealership has been involved in verifies the correction or notifications to the end user.

Hamilton as attached the instruction on how to correct the issue without any new parts:

All New 98RH Heads Shipped After 8/13/12 and With a Serial Number of #2525-N and Higher Will Have a Stainless Steel Spacer Welded in Place.