



## TECHNICAL BULLETIN

Support Number: 513-874-3733

Fax: 513-874-6232

Web Site: [www.hamiltonsafe.com](http://www.hamiltonsafe.com)

Email: [support@hamiltonsafe.com](mailto:support@hamiltonsafe.com)

Author:  
Bill Detherage

Bulletin #  
HA33\_00.01

Verification:  
Dion Cullum

Date Issued:  
7/30/07

Product:  
HA33

Date Revised:

Subject:

### Upgrade software for HA33 with Hamilton controls

All,

The HA33 units that shipped 6/12/07 and after with a serial number 554 and greater were fitted with a programmable logic control boards that were designed and manufactured by Hamilton. The software and boards have been through a few minor changes during this time to help with operation. Recently we have made some significant software changes in the last revision that we feel warrants this notice to all dealers. These changes make the software much more robust and less likely to have any failures. Hamilton strongly suggests that new software chips be ordered and replaced in all the machines using this system.

The chip can be replaced very easily by accessing the control panel, disconnecting power, remove old chip and replace with new chip, restoring power to both ends after both chips are replaced.

The software chips are available immediately from Hamilton at no charge.

**E0899 = Programmable Software Chip Rev. 1.01.00**